

安全评价报告信息网上公示

项目概况	项目名称	共和县祁连山金河水泥有限责任公司江仓龙洼大理岩矿安全设施现状评价报告		
	行业类别	非煤矿山	报告提交时间	2023. 8. 26
	项目简介	共和县祁连山金河水泥有限责任公司江仓龙洼大理岩矿位于青海省海南州共和县恰卜恰镇北直距约 20km 处尕寺村江仓龙洼一带。该矿山为山坡露天矿，生产规模为 30 万 m ³ /a。采用公路+溜槽联合开拓、汽车运输方案，采矿方法采用自上而下，台阶式开采，该矿山共形成 10 个平台。其中 4 个安全平台，1 个清扫平台，1 个采矿平台，1 个溜矿平台，3 个装矿平台。该矿山《安全生产许可证》需要延期换证。按照《非煤矿山企业安全生产许可证实施办法》的要求，为延续安全生产许可证，该公司委托我公司开展安全设施现状评价工作。		
安全评价项目参与人员	项目评价组长	崔振廷	技术负责人	赵全平
	过程控制负责人	何海霞	报告编制人	崔振廷
	报告审核人	党玲灵	安全评价师	崔振廷、潘甜、余江河、周会平、逯冬、李存宝、芦文晖
	注册安全工程师	余江河、李存宝、芦文晖	技术专家	何宗仁、陈宜强
评价活动主要信息	安全评价类型	安全现状评价报告		
	到现场评价人员	崔振廷、芦文晖		
	到现场时间及任务	于 2023 年 08 月 14 日前往现场进行实地勘察和收集基础资料		

		 采矿边坡
	现场照片	 3645m 采矿平台  3630m 装矿平台



矿山道路



道路排水沟



1 号溜槽

		A photograph showing a concrete barrier structure at the top of a溜槽 (chute) in a mountainous area under a cloudy sky. 溜槽上口车挡 A photograph of a road with a convex mirror mounted on a post, reflecting the road ahead, with a steep rocky hillside in the background. 道路凸面镜 A photograph of a避险车道 (emergency escape lane) on a mountain road, showing a paved area and a steep hillside. 避险车道
	备注及其他 信息	